

KNX IP-Router

Änderungsprotokoll



Hinweis

Bitte beachten Sie, dass IP-Router der ersten Generation ohne Software-Update nicht kompatibel zur Datenbank der Version 2 sind! Der Router stoppt dann sein Applikationsprogramm! In diesem Fall kann das Gerät durch Laden der korrekten Applikation (Version 1) via Twisted Pair wieder hergestellt werden.

Software-Update V2.0

- Beim Programmieren eines externen KNX-Teilnehmers wird die Verbindung unter Umständen nicht richtig beendet.
- Routing busy (IP) standardmäßig auf **AUS** gestellt.
- Mehrere Geräte im Programmiermodus – eventuell wurden mehrere Geräte im Programmiermodus angezeigt.

Change log



Note

Please note that first-generation IP routers without a software update are not compatible with the Version 2 database! The router then stops its application program! In this case, the device can be restored by loading the correct application (Version 1) via twisted pair.

Software update V2.0

- When programming an external KNX device, the connection may not be ended correctly.
- Routing busy (IP) set to **OFF** as a default.
- Several devices in programming mode - it was possible for several devices to be displayed in programming mode.